



CHEROKEE NATION  
Environmental Programs

---

# LEAD-BASED PAINT INSPECTION & RISK ASSESSMENT REPORT

**Conducted At:**

Name: Prather, John  
Address: 15780 East 500 Rd  
City State Zip: Claremore, OK 74019  
Coordinates: 35.95423, -95.46827  
Built In: 1968

**Prepared For:**

HACN Housing Rehabilitation - George Hubbard  
Using ODEQ, EPA and CN Work Practice Standards  
Established in 40 CFR 745-227

**Inspected By:**

*Chris Cochran*

*2/12/24*

Chris Cochran  
OKRASR13995, CNRASR00038

Cherokee Nation Environmental Programs  
PO Box 948, Tahlequah, OK 74465  
(918) 453-5000  
Oklahoma Firm: OKFIRM11198  
Cherokee Nation Firm: CNFIRM00001

Report Date: February 12, 2024

# CONTENTS

<b>1.0 EXECUTIVE SUMMARY.....</b>	<b>3</b>
<b>2.0 DISCLOSURE .....</b>	<b>3</b>
<b>3.0 INSPECTION/ RISK ASSESSMENT METHODOLOGY.....</b>	<b>4</b>
3.1 Surface-by-Surface Inspection Methodology .....	4
3.2 X-Ray Fluorescence Analyzer Lead Detector .....	4
3.3 Risk Assessment Methodology.....	4
3.4 Description of Paint Condition Hazard Rankings .....	5
3.5 Laboratory Analysis .....	5
<b>4.0 DESCRIPTION OF RESULTS.....</b>	<b>5</b>
4.1 LBP Inspection .....	6
4.2 LBP Risk Assessment.....	6
4.3 Resident Questionnaire Form 5.0.....	6
4.4 Building Condition Form 5.1.....	7
4.5 Dust Wipe Sample Analysis.....	8
4.6 Soil Sample ANALYSIS .....	8
<b>5.0 RECOMMENDATIONS .....</b>	<b>9</b>
5.1 Deteriorated Lead-Based Paint .....	9
5.2 Lead Dust Control Options .....	9
5.3 Lead in Soil .....	10
<b>6.0 Re-evaluation and Monitoring Schedule .....</b>	<b>10</b>
<b>APPENDIX A: XRF Field Data Sheets &amp; Floor Plan.....</b>	<b>11</b>
<b>APPENDIX B: Dust Wipe &amp; Soil Analysis.....</b>	<b>12</b>
<b>APPENDIX C: Scope of Work/Request .....</b>	<b>13</b>

## 1.0 EXECUTIVE SUMMARY

A lead based paint inspection was conducted at the John Prather site on February 2<sup>nd</sup>, 2024 as requested by the Cherokee Nation Housing Rehabilitation Department. The inspection **confirmed the presence of lead** in amounts greater than or equal to 1.0 mg/cm<sup>2</sup> in paint, using the inspection protocol in Chapter 7 of the U.S. Department of Housing and Urban Development's (HUD) Guidelines for the Evaluation of Control of Lead-Based Paint Hazards in Housing (2012). A Risk Assessment was performed to fulfill the requirements for a federally assisted rehabilitation.

The full inspection report can be found in Appendix A (XRF Field Data Sheets). Building components that were unable to be tested with an XRF and are assumed positive include the following:

N/A

**The following is a summary of the survey findings for the subject property:**

### **Interior Lead-Based Paint**

No lead in paint identified.

### **Exterior Lead-Based Paint**

Soffits A and D sides

Fascia D side

### **Deteriorated Lead-Based Paint (Lead-Based Paint Hazards)**

Soffits A and D Side

Fascia D side

### **Lead in Dust Hazards**

Lead in dust hazards were identified in Bathroom Window Sill.

### **Lead in Soil Hazards**

No lead in soil hazards were identified.

*This executive summary has been prepared for the convenience of the users of this report. This summary does not contain all the information presented in this report and, therefore, the entire report should be read to assure all pertinent information is transmitted.*

## 2.0 DISCLOSURE

A copy of this report or a summary of this report must be provided to new lessees (tenants) and purchasers of the property under Federal law (24 CFR part 35 and 40 CFR part 745) before they become

obligated under a lease or sales contract. The complete report must also be provided to new purchasers and it must be made available to new tenants. Property owners (lessors) and sellers are also required to distribute an educational pamphlet approved by the US Environmental Protection Agency (EPA) and include standard warning language in their leases or sales contracts to ensure that parents have the information they need to protect their children from lead-based paint hazards

### 3.0 INSPECTION/ RISK ASSESSMENT METHODOLOGY

#### 3.1 SURFACE-BY-SURFACE INSPECTION METHODOLOGY

A surface-by-surface lead-based paint inspection was performed to identify interior and exterior building components finished with lead-based paint. The inspection was performed inside the residence and on exterior surfaces of the residence using a portable X-Ray Fluorescence Analyzer (XRF). The inspection was limited to accessible painted and/or varnished surfaces. All substrates within inaccessible rooms are assumed positive for lead-based paint until access is available to prove otherwise.

The inspection was conducted in accordance with the EPA's work practice standards for conducting lead-based paint activities (40 CFR 745.227), HUD's Guidelines for the Evaluation and Control of Lead-Based Paint Hazards in Housing (Guidelines) with the 2012 revisions. Samples were collected to represent component types; therefore, it should be assumed that similar component types in the rest of that room or room equivalent also contain lead-based paint. When standing in any four-sided room facing side A, which coincides with the front of the dwelling, side B will be to the right, side C will be to the rear, and side D will be to the left (clockwise from side A).

When evaluating this report it is assumed that, according to Chapter 7 HUD Guidelines, if one testing combination (i.e. window, door) is positive for lead in an interior or exterior room equivalent, all other similar testing combinations in those areas are assumed to be positive. The same is true for negative readings.

#### 3.2 X-RAY FLUORESCENCE ANALYZER LEAD DETECTOR

The sampling strategy utilized to determine the presence of lead-based paint adheres to the EPA Performance Characteristic Sheet for the particular XRF instrument used, as well as the manufacturers' modifications and recommendations. The Heuresis PB200i lead x-ray fluorescence analyzer (Serial Number: 2312) was used for detection of building components finished with lead-based paint. The instrument was manufactured by Viken Detection, 21 North Avenue, Burlington, MA 01803. The radioactive source is cobalt-57 and was last resourced on August 26, 2021.

Samples may be classified as positive or negative. Positive results indicate lead in quantities greater than 1.0 mg/cm<sup>2</sup> and are considered lead-based paint. Negative results indicate lead in quantities less than 1.0 mg/cm<sup>2</sup> and are not considered lead-based paint.

#### 3.3 RISK ASSESSMENT METHODOLOGY

The lead-based paint risk assessment was performed to determine if the lead-based paint present in the residence presents an immediate hazard. This was accomplished through combining measurements of lead in dust, surface-by-surface paint analysis, visual assessment of the residence, assessment of paint

condition, and by collecting maintenance and management data to identify and address lead-based paint hazards.

The risk assessment was performed in accordance with the EPA's work practice standards for conducting lead-based paint activities (40 CFR 745.227), HUD's Guidelines for the Evaluation and Control of Lead-Based Paint Hazards in Housing (Guidelines) with the 2012 revisions.

### 3.4 DESCRIPTION OF PAINT CONDITION HAZARD RANKINGS

The paint condition is placed into one of two categories using the risk assessor's professional judgment. These categories are intact or deteriorated. Type of deterioration may also be noted on surfaces in deteriorated condition. Based on the approximate surface area of deteriorated paint, the risk assessor then assesses the paint condition as intact or deteriorated. These conditions indicate the potential for lead hazards associated with paint condition and lead in household dust.

Hazard ranking protocol was performed in accordance with the HUD Guidelines for Evaluation and Control of Lead-Based Paint Hazards in Housing, dated July 2012, Chapter 5: Risk Assessment and Reevaluation; Identification of Deteriorated Paint (Form 5.2). This information is summarized below.

#### ***Deteriorated***

*EPA regulations define deteriorated paint as "any interior or exterior paint or other coating that is peeling, chipping, chalking, or cracking, or any paint or coating located on an interior or exterior surface or fixture that is otherwise damaged or separated from the substrate" (40 CFR 745.63).*

### 3.5 LABORATORY ANALYSIS

Laboratory analysis of dust wipe/soil samples were performed by QuanTem Laboratories (NLLAP 101352), 2033 Heritage Park Drive, Oklahoma City, OK 73120 Phone: 405-755-7272. Laboratory analysis of the dust wipes and soil samples are analyzed based on the EPA SW846-7420/ HUD -- Flame Atomic Absorption.

## 4.0 DESCRIPTION OF RESULTS

This is a report of an X-ray Fluorescence (XRF) inspection and risk assessment to determine if lead-based paint exists in the readily accessible areas of this residence and tested components. The presence or absence of lead-based paint only applies to surfaces tested or assessed on the date of the field visit. According to HUD/EPA Guidelines, paint with concentrations of lead that exceed 1.0 mg/cm<sup>2</sup> must be considered a lead-based paint (LBP). However, detectable lead in quantities less than 1.0 mg/cm<sup>2</sup> may contribute to the development of lead dust hazards even though it is not considered a lead-based paint hazard.

#### 4.1 LBP INSPECTION

Lead based paint was found on both the interior and exterior of the site. The positive readings are shown in the following table. The full report with all readings are in Appendix 1.

ID	Reading	Unit	Location	Material	Condition	Notes
83	2.3	mg/cm2	Exterior	Soffit	Wood	A Deteriorated
91	1.2	mg/cm2	Exterior	Soffit	Wood	D deteriorated
92	1.2	mg/cm2	Exterior	Fascia	Wood	D deteriorated

#### 4.2 LBP RISK ASSESSMENT

Lead-based paint hazards and dust hazards were identified during the survey.

The lead hazards are:

- Exterior Soffit A and D Sides (B and C are enclosed.)
- Exterior Fascia D Side

Lead in Dust Hazards

- Bathroom Window Sill

Lead in Soil Hazards

- 

#### 4.3 RESIDENT QUESTIONNAIRE FORM 5.0

A resident questionnaire was completed as part of the Assessment, to help identify particular use patterns, which may be associated with potential LBP hazards, such as opening and closing windows painted with LBP. The answers to the questionnaire were obtained during an interview with the occupants. Following is a summary of the information obtained during the interview.

Children in the Household:	None
Children's bed locations:	-
Children's eating locations:	-
Primary interior play area(s):	-
Primary exterior play area(s):	-
Pets:	-
Blood lead testing history:	-
Observed chewed surfaces:	-
Women of child bearing age:	0
Previous lead testing:	None
Frequently used entrances:	Front Door
Frequently opened windows:	None
Structure Cooling Method:	Central Heat and Air

Gardening –type and location: none  
 Plans for landscaping: None  
 Cleaning regiment: Weekly  
 Cleaning Methods: Mopping, sweeping, dusting, vacuuming  
 Recent completed renovations: None  
 Demolition debris on site: None  
 Resident with work lead exposure: None  
 Planned Renovations: A scope of work document for this residence is included in Appendix C.

#### 4.4 BUILDING CONDITION FORM 5.1

Condition	Yes	No	Comments
Roof is missing parts of surfaces (tiles, boards, shakes, etc.)		X	
Roof has holes or large cracks		X	
Gutters or downspouts broken		X	
Chimney masonry cracked, bricks loose or missing, obviously out of plumb.		X	
Exterior or interior walls have obvious large cracks or holes, requiring more than routine painting.		X	
Exterior siding has missing boards or shingles		X	
Water stains on interior walls or ceilings		X	
Walls or ceilings deteriorated		X	
More than "very small*" amount of paint in a room deteriorated		X	
Two or more windows or doors broken, missing, or boarded up		X	
Porch or steps have major elements broken, missing, or boarded up.		X	
Foundation has major cracks, missing material, structure leans, or visibly unsound		X	
Total Number		12	

\*The "very small" amount is the de minimis amount under the HUD Lead Safe Housing Rule (24 CFR 35.1350(d)), or the amount of paint that is not "paint in poor condition" under the EPA lead training and certification ("402") rule (40 CFR 745.223)

Notes (including other conditions of concern):

#### 4.5 DUST WIPE SAMPLE ANALYSIS

Dust wipe samples were collected in an effort to help determine the levels of lead-containing dust on the interior windowsills and floors. The following tables note the presence or absence of lead hazards in dust per the EPA risk assessment and clearance standards. Please refer to Appendix B for detailed analytical reports. The presence of these hazards indicates that sample results exceed the following EPA criteria:

- 10 ug/ft<sup>2</sup> for floors, including carpeted floors
- 100 ug/ft<sup>2</sup> for interior window sills
- 100 ug/ft<sup>2</sup> for interior window troughs

The following table indicates the sample number, location, surface type, lead concentration, and presence or absence of lead dust hazards for dust wipe samples collected during this LBP Risk Assessment:

<b>Dust Wipe Sample Analysis</b>				
<b>Sample #</b>	<b>Location</b>	<b>Surface Types</b>	<b>Concentration (Micrograms/ft<sup>2</sup>)</b>	<b>Lead Hazard</b>
01	Kitchen	Floor	<2.0	NO
02	Kitchen	Window Sill	<9.0	NO
03	Laundry Room	Floor	<2.0	NO
04	Laundry Room	Window Sill	11	NO
05	Bath Room	Floor	<2.0	NO
06	Bath Room	Window Sill	3100	YES
07	Porch	Floor	2.6	NO

#### 4.6 SOIL SAMPLE ANALYSIS

The EPA has established lead hazard standards for lead in soil under TSCA Section 403 (Residential Lead Hazards). Please refer to Appendix B for detailed analytical reports. The following level of lead in soil should be considered hazardous and may result in excessive lead exposure and elevated blood lead levels:

- 400 milligrams per kilogram (mg/Kg) in children's play areas with bare residential soil (e.g., sandboxes, gardens)
- 1,200 mg/Kg (average) in bare soil for the remainder of the yard.



The following table indicates the sample number, location, surface type, lead concentration, and presence or absence of lead soil hazards for soil samples collected during this LBP Risk Assessment:

Soil Sample Analysis				
Sample #	Location	Bare or Covered	Concentration (Micrograms/ft <sup>2</sup> )	Lead Hazard
09	Dripline	Bare	33	NO

## 5.0 RECOMMENDATIONS

### 5.1 DETERIORATED LEAD-BASED PAINT

Room or Exterior Location	Component	Type of Hazard	Approximate Area or Length	Acceptable Hazard Control Options	
				Interim	Abatement
Exterior Side A and D	Soffit	Paint		Wet scrape/Repaint	Replace or Enclose
Exterior Side D	Fascia	Paint		Wet scrape/Repaint	Replace or Enclose

### 5.2 LEAD DUST CONTROL OPTIONS

Room	Surface	Acceptable Hazard Control Method
Bathroom	Window Sill	Hepa/Wet/Hepa

### 5.3 LEAD IN SOIL

Type Of Area	Location	Acceptable Hazard Control Options	

### 6.0 RE-EVALUATION AND MONITORING SCHEDULE

Each of these treatments will need to be reexamined periodically to make certain that they remain effective and to ensure that new lead-based paint hazards do not appear. The interim controls shown above are less expensive initially, but they may be more expensive in the end since they need to be reevaluated more frequently. The replacement and paint removal methods are more expensive initially, but do not require any reevaluation.

The owner should monitor the condition of the paint at least annually or if there is some indication, that paint might be failing. A professional reevaluation is also needed. The standard schedule for reevaluation the dwelling is shown above.

**Re-evaluation:** Standard Re-evaluation Schedule 3 contained in the HUD Guidelines applies to this property, since one of the rooms had a dust lead level greater than the standard. Therefore, the dwelling should be reevaluated in February 2025 (12 months from now). If no lead-based paint hazards are identified at that time, another reevaluation should be conducted in February 2026 (2 years later). If no lead-based paint hazards are identified at that time, no further reevaluations are needed. However, since lead-based paint may be present in the dwelling, the owner should monitor the condition of all painted surfaces at least annually or whenever other information indicates a potential problem.

## APPENDIX A: XRF Field Data Sheets & Floor Plan

Viken Detection

Ph200i

XRF Lead Paint Analyzer

2312

Ph200i-5.3.1

Readir	Concentra	Units	3 SD	Result	Norms	Date	Time	Room/CI	Structure	Member	Substrate	Wall	Condition
4	0.2	mg/cm2	0.2	Negative	2	2/2/2024	12:08:16	Living Roo	Room	Wall	Wood1	A1	Intact
5	0.2	mg/cm2	0.3	Negative	2	2/2/2024	12:08:27	Living Roo	Room	Wall	Wood2	A2	Intact
6	0.2	mg/cm2	0.2	Negative	2	2/2/2024	12:08:40	Living Roo	Room	Wall	Wood3	A3	Intact
7	0.4	mg/cm2	0.2	Negative	2	2/2/2024	12:09:06	Living Roo	Room	Wall	Wood4	A4	Intact
8	0.4	mg/cm2	0.2	Negative	2	2/2/2024	12:09:34	Living Roo	Room	Ceiling	Drywall1		1 Intact
9	0.2	mg/cm2	0.2	Negative	2	2/2/2024	12:10:08	Living Roo	Room	Baseboard	Wood1	A1	Intact
10	0.1	mg/cm2	0.2	Negative	2	2/2/2024	12:10:36	Living Roo	Door	Wood2	Wood2	A2	Intact
11	0.2	mg/cm2	0.2	Negative	2	2/2/2024	12:10:55	Living Roo	Door	Jamb	Wood3	A3	Intact
12	0.1	mg/cm2	0.3	Negative	2	2/2/2024	12:12:01	Living Roo	Window	Sill	Wood4	D1	Intact
13	0.1	mg/cm2	0.2	Negative	2	2/2/2024	12:12:43	Bedroom	Window	Sill	Wood5	A1	Intact
14	0.3	mg/cm2	0.2	Negative	2	2/2/2024	12:13:10	Bedroom	Door	Wood6	Wood6	D1	Intact
15	0.2	mg/cm2	0.2	Negative	2	2/2/2024	12:13:27	Bedroom	Door	Jamb	Wood7	D2	Intact
16	0.2	mg/cm2	0.2	Negative	2	2/2/2024	12:13:46	Bedroom	Room	Baseboard	Wood8	D3	Intact
17	0.3	mg/cm2	0.2	Negative	2	2/2/2024	12:14:16	Bedroom	Room	Ceiling	Drywall1		1 Intact
18	0.3	mg/cm2	0.2	Negative	2	2/2/2024	12:14:46	Bedroom	Room	Wall	Wood1	A1	Intact
19	0.3	mg/cm2	0.2	Negative	2	2/2/2024	12:15:02	Bedroom	Room	Wall	Wood2	A2	Intact
20	0.2	mg/cm2	0.2	Negative	2	2/2/2024	12:15:12	Bedroom	Room	Wall	Wood3	A3	Intact
21	0.2	mg/cm2	0.3	Negative	2	2/2/2024	12:15:30	Bedroom	Room	Wall	Wood4	A4	Intact
22	0.2	mg/cm2	0.3	Negative	2	2/2/2024	12:16:28	Bedroom	Room	Wall	Wood5	A5	Intact
23	0.2	mg/cm2	0.3	Negative	2	2/2/2024	12:16:41	Bedroom	Room	Wall	Wood6	A6	Intact
24	0.2	mg/cm2	0.3	Negative	2	2/2/2024	12:16:56	Bedroom	Room	Wall	Wood7	A7	Intact
25	0	mg/cm2	0.2	Negative	3	2/2/2024	12:17:06	Bedroom	Room	Wall	Wood8	A8	Intact
26	0.1	mg/cm2	0.2	Negative	2	2/2/2024	12:17:30	Bedroom	Room	Ceiling	Drywall1		1 Intact
27	0.1	mg/cm2	0.2	Negative	2	2/2/2024	12:18:01	Bedroom	Room	Baseboard	Wood1	C1	Intact

28	0.3 mg/cm2	0.2 Negative	2	2/2/2024	12:18:25	Bedroom ; Door	Wood2	C2	Intact
29	0.1 mg/cm2	0.2 Negative	2	2/2/2024	12:18:39	Bedroom ; Door	Wood3	C3	Intact
30	0 mg/cm2	0.2 Negative	2	2/2/2024	12:19:11	Bedroom ; Window	Wood4	A1	Intact
31	0.2 mg/cm2	0.2 Negative	2	2/2/2024	12:20:04	Bathroom Cabinets	Wood5	D1	Intact
32	0.1 mg/cm2	0.2 Negative	2	2/2/2024	12:20:22	Bathroom Cabinets	Wood6	D2	Intact
33	0.1 mg/cm2	0.2 Negative	2	2/2/2024	12:21:36	Bathroom Window	Wood7	C1	Intact
34	0.1 mg/cm2	0.2 Negative	2	2/2/2024	12:22:06	Bathroom Door	Wood8	A1	Intact
35	0.2 mg/cm2	0.2 Negative	2	2/2/2024	12:22:23	Bathroom Door	Wood9	A2	Intact
36	0.1 mg/cm2	0.2 Negative	2	2/2/2024	12:22:47	Bathroom Room	Baseboard Wood10	A3	Intact
37	0.1 mg/cm2	0.2 Negative	2	2/2/2024	12:23:15	Bathroom Room	Ceiling Drywall1	1	Intact
38	0.2 mg/cm2	0.2 Negative	2	2/2/2024	12:23:39	Bathroom Room	Wall Drywall2	A1	Intact
39	0.1 mg/cm2	0.2 Negative	2	2/2/2024	12:23:50	Bathroom Room	Wall Drywall3	A2	Intact
40	0.2 mg/cm2	0.2 Negative	2	2/2/2024	12:24:00	Bathroom Room	Wall Drywall4	A3	Intact
41	0.3 mg/cm2	0.3 Negative	2	2/2/2024	12:24:09	Bathroom Room	Wall Drywall5	A4	Intact
42	0.2 mg/cm2	0.2 Negative	2	2/2/2024	12:24:54	Den	Wall Wood1	A5	Intact
43	0.1 mg/cm2	0.2 Negative	2	2/2/2024	12:25:05	Den	Wall Wood2	A6	Intact
44	0.2 mg/cm2	0.2 Negative	2	2/2/2024	12:25:25	Den	Wall Wood3	A7	Intact
45	0.1 mg/cm2	0.3 Negative	2	2/2/2024	12:25:40	Den	Wall Wood4	A8	Intact
46	0.2 mg/cm2	0.2 Negative	2	2/2/2024	12:26:06	Den	Ceiling Drywall1	1	Intact
47	0.2 mg/cm2	0.2 Negative	2	2/2/2024	12:26:36	Den	Baseboard Wood1	A1	Intact
48	0.1 mg/cm2	0.2 Negative	2	2/2/2024	12:26:55	Den	Wood2	A2	Intact
49	0.1 mg/cm2	0.2 Negative	2	2/2/2024	12:27:11	Den	Wood3	A3	Intact
50	0.1 mg/cm2	0.3 Negative	2	2/2/2024	12:28:17	Laundry R; Window	Jamb Wood4	C1	Intact
51	0 mg/cm2	0.2 Negative	2	2/2/2024	12:28:41	Laundry R; Door	Sill Wood5	C2	Intact
52	0 mg/cm2	0.2 Negative	2	2/2/2024	12:28:58	Laundry R; Door	Jamb Wood6	C3	Intact
53	0.2 mg/cm2	0.3 Negative	2	2/2/2024	12:29:23	Laundry R; Room	Baseboard Wood7	A1	Intact
54	0.2 mg/cm2	0.2 Negative	2	2/2/2024	12:29:48	Laundry R; Room	Ceiling Drywall1	1	Intact
55	0.2 mg/cm2	0.3 Negative	2	2/2/2024	12:30:09	Laundry R; Room	Wall Drywall2	A1	Intact
56	0.2 mg/cm2	0.2 Negative	2	2/2/2024	12:30:23	Laundry R; Room	Wall Drywall3	A2	Intact
57	0.2 mg/cm2	0.2 Negative	2	2/2/2024	12:30:38	Laundry R; Room	Wall Drywall4	A3	Intact
58	0.2 mg/cm2	0.3 Negative	2	2/2/2024	12:30:51	Laundry R; Room	Wall Drywall5	A4	Intact
59	0.2 mg/cm2	0.2 Negative	2	2/2/2024	12:31:22	Bathroom Room	Wall Drywall6	A5	Intact
60	0.2 mg/cm2	0.3 Negative	2	2/2/2024	12:31:32	Bathroom Room	Wall Drywall7	A6	Intact
61	0.2 mg/cm2	0.2 Negative	2	2/2/2024	12:31:40	Bathroom Room	Wall Drywall8	A7	Intact

62	0.2 mg/cm2	0.2 Negative	2	2/2/2024	12:31:50	Bathroom Room	Wall	Drywall9	A8	Intact
63	0.2 mg/cm2	0.2 Negative	2	2/2/2024	12:32:09	Bathroom Room	Ceiling	Drywall10	1	Intact
64	0.3 mg/cm2	0.2 Negative	2	2/2/2024	12:32:32	Bathroom Room	Baseboard	Wood1	B1	Intact
65	0.1 mg/cm2	0.2 Negative	2	2/2/2024	12:32:50	Bathroom Door	Jamb	Wood2	B2	Intact
66	0.2 mg/cm2	0.2 Negative	2	2/2/2024	12:33:06	Bathroom Door	Jamb	Wood3	B3	Intact
67	0.1 mg/cm2	0.2 Negative	2	2/2/2024	12:33:36	Bathroom Window	Sill	Wood4	D1	Intact
68	0.2 mg/cm2	0.2 Negative	2	2/2/2024	12:34:08	Bathroom Cabinets	Door	Wood5	C1	Intact
69	0.1 mg/cm2	0.2 Negative	2	2/2/2024	12:34:25	Bathroom Cabinets	Frame	Wood6	C2	Intact
70	0.2 mg/cm2	0.2 Negative	2	2/2/2024	12:35:25	Kitchen/Di Cabinets	Door	Wood7	B1	Intact
71	0.2 mg/cm2	0.2 Negative	2	2/2/2024	12:35:42	Kitchen/Di Cabinets	Frame	Wood8	B2	Intact
72	0.2 mg/cm2	0.2 Negative	2	2/2/2024	12:36:09	Kitchen/Di Window	Sill	Wood9	B3	Intact
73	0 mg/cm2	0.2 Negative	2	2/2/2024	12:36:34	Kitchen/Di Door	Jamb	Wood10	B4	Intact
74	0.1 mg/cm2	0.2 Negative	2	2/2/2024	12:37:01	Kitchen/Di Room	Baseboard	Wood11	A1	Intact
75	0.5 mg/cm2	0.2 Negative	2	2/2/2024	12:37:29	Kitchen/Di Room	Ceiling	Drywall1	1	Intact
76	0.2 mg/cm2	0.2 Negative	2	2/2/2024	12:37:58	Kitchen/Di Room	Wall	Wood1	A1	Intact
77	0.2 mg/cm2	0.2 Negative	2	2/2/2024	12:38:14	Kitchen/Di Room	Wall	Wood2	A2	Intact
78	0 mg/cm2	0.2 Negative	2	2/2/2024	12:38:25	Kitchen/Di Room	Wall	Wood3	A3	Intact
79	0.2 mg/cm2	0.2 Negative	2	2/2/2024	12:38:44	Kitchen/Di Room	Wall	Wood4	A4	Intact
80	0.1 mg/cm2	0.2 Negative	2	2/2/2024	12:41:56	Door	Door	Wood5	A5	Intact
81	0.2 mg/cm2	0.2 Negative	3	2/2/2024	12:42:13	Door	Jamb	Wood6	A6	Intact
82	0.5 mg/cm2	0.2 Negative	2	2/2/2024	12:42:59	Window	Exterior Ce	Wood7	A7	Intact

83	1.2 mg/cm2	0.2 Positive	5	2/2/2024	12:53:52	Window	Exterior Ce	Wood15	C3	Intact
84	0 mg/cm2	0.2 Negative	2	2/2/2024	12:44:58	Fascia		Wood9	A9	Intact
85	0.2 mg/cm2	0.2 Negative	2	2/2/2024	12:45:56	Door		Wood10	B1	Intact
86	0.2 mg/cm2	0.2 Negative	2	2/2/2024	12:46:16	Door	Jamb	Wood11	B2	Intact
87	0.2 mg/cm2	0.2 Negative	2	2/2/2024	12:46:47	Window	Exterior Ce	Wood12	B3	Intact
88	0 mg/cm2	0.2 Negative	2	2/2/2024	12:47:58	Fascia		Wood13	C1	Intact
89	0.2 mg/cm2	0.2 Negative	2	2/2/2024	12:48:46	Softit		Wood14	C2	Intact
90	0.2 mg/cm2	0.2 Negative	2	2/2/2024	12:50:02	Window	Exterior Ce	Wood15	C3	Intact

1-13 mg/cm2 0.1  
 11 mg/cm2 0.1  
 15 mg/cm2 0.1

## APPENDIX B: DUST WIPE & SOIL ANALYSIS



2033 HERITAGE PARK DR, OKLAHOMA CITY, OK 73120 | 1.800.822.1650

## Environmental Chemistry Analysis Report

QuanTEM Set ID: 366120  
 Date Received: 02/06/24  
 Received By: Baylie Longstreth  
 Date Sampled:  
 Time Sampled:  
 Analyst:  
 Date of Report: 02/07/24  
 AIHA LAP, LLC: 101352

Client: Cherokee Nation Environmental Programs  
 Chris Cochran  
 PO Box 948  
 Tablequah, OK 74464  
 Acct. No.: C162  
 Project: John Prather  
 Location: Claremore  
 Project No.: N/A

QuantEM ID	Client ID	Matrix	Parameter	Results	Reporting Limits	Units	Date/Time Analyzed	Method
001	01	Wipe	Lead	<2.0	**	ug/sq. Ft.	02/07/24 0:00	NIOSH 7082
002	02	Wipe	Lead	<9.0	**	ug/sq. Ft.	02/07/24 0:00	NIOSH 7082
003	03	Wipe	Lead	<2.0	**	ug/sq. Ft.	02/07/24 0:00	NIOSH 7082
004	04	Wipe	Lead	11	**	ug/sq. Ft.	02/07/24 0:00	NIOSH 7082
005	05	Wipe	Lead	<2.0	**	ug/sq. Ft.	02/07/24 0:00	NIOSH 7082
006	06	Wipe	Lead	3100	**	ug/sq. Ft.	02/07/24 0:00	NIOSH 7082
007	07	Wipe	Lead	2.6	**	ug/sq. Ft.	02/07/24 0:00	NIOSH 7082
008	08	Soil	Lead	33	**	mg/kg	02/07/24 0:00	Soil EPA 7000B (1)

Note: Sample results have not been corrected for blank values.

This report applies only to the standards or procedures indicated and to the specific samples tested. It is not indicative of the qualities of apparently identical or similar products or procedures, nor does it represent an ongoing assurance program unless so noted. These reports are for the exclusive use of the client and are not to be reproduced without specific written permission. QuantEM is not responsible for user-supplied data used in calculations. Customer provided data such as volumes, areas, etc., cannot be verified by QuantEM Laboratories, LLC.

Unless otherwise noted, upon receipt the condition of the sample was acceptable for analysis.

Wipe materials must meet ASTM E1792 criteria. Method detection limits and resultant reporting limits may not be valid for non-ASTM E1792 wipe material.

EPA Method 7000B (1) = EPA 600/R-93/200 Preparation Modified. EPA 7000B Analysis Modified

EPA Method 7082 (2) = EPA 600/R-93/200 Preparation Modified. EPA 7082 Analysis Modified





2033 HERITAGE PARK DR, OKLAHOMA CITY, OK 73120 | 1.800.822.1650

## Environmental Chemistry Analysis Report

QuantEM Set ID: 366120  
Date Received: 02/06/24  
Received By: Baylie Longstreth  
Date Sampled:  
Time Sampled:  
Analyst:  
Date of Report: 02/07/24  
AIHA LAP, LLC: 101352

Client: Cherokee Nation Environmental Programs  
Chris Cochran  
PO Box 948  
Tahlequah, OK 74464  
Acct. No.: C162  
Project: John Prather  
Location: Claremore  
Project No.: N/A

QuantEM ID	Client ID	Matrix	Parameter	Results	Reporting Limits	Units	Date/Time Analyzed	Method
------------	-----------	--------	-----------	---------	------------------	-------	--------------------	--------

\*\*Report Limit for an undiluted 50ml sample is 4ug Total Pb.

\*\*Report Limit for an undiluted 25 ml sample is 2ug Total Pb.

Analysis performed by Scientific Analytical Institute, Inc, Greensboro, NC  
AIHA LAP Laboratory ID: LAP-173190

The quality control samples run with the samples in this report have passed all EPA required specifications unless otherwise noted.

Authorized Signature: \_\_\_\_\_

Dee Ammerman, Laboratory Manager

Note: Sample results have not been corrected for blank values.


This report applies only to the standards or procedures indicated and to the specific samples tested. It is not indicative of the qualities of apparently identical or similar products or procedures, nor does it represent an ongoing assurance program unless so noted. These reports are for the exclusive use of the client and are not to be reproduced without specific written permission. QuantEM is not responsible for user-supplied data used in calculations. Customer provided data such as volumes, areas, etc., cannot be verified by QuantEM Laboratories, LLC.

Unless otherwise noted, upon receipt the condition of the sample was acceptable for analysis.

Wipe materials must meet ASTM E1792 criteria. Method detection limits and resultant reporting limits may not be valid for non-ASTM E1792 wipe material.

EPA Method 7000B (1) - EPA 600/R-93/200 Preparation Modified. EPA 7000B Analysis Modified

EPA Method 7082 (2) - EPA 600/R-93/200 Preparation Modified. EPA 7082 Analysis Modified



www.Quantem.com

**LEAD CHAIN OF CUSTODY**  
 2033 Heritage Park Drive, Oklahoma City, OK 73120-7502  
 (800) 822-1650 • (405) 755-7272 • Fax (405) 755-2058  
**LEGAL DOCUMENT - PLEASE PRINT LEGIBLY**

For Lab Use Only  
 Lab No. 266100  
 Accept  Reflect

<b>Contact Information</b>		<b>Project Information</b>	
Company: Cherokee Nation Environmental Programs	Phone: (918) 453-5009	Project Name: John Prather	Report Results <input type="checkbox"/> See Box
Contact:	Cell Phone: (918) 316-7452	Project Location: Claremore	<input checked="" type="radio"/> Quantem Website
Account #: C162	E-mail: <a href="mailto:christopher-cochran@cherokee.org">christopher-cochran@cherokee.org</a>	Project ID:	<input type="radio"/> Email: <a href="mailto:christopher-cochran@cherokee.org">christopher-cochran@cherokee.org</a>
Sampled By: Name: Christopher Cochran	Date: 02/05/2024	PO Number: 874812	<input type="radio"/> Other
RELINQUISHED BY	DATE & TIME	VIA	RECEIVED BY
Christopher Cochran	2/05/2025	Fed Ex	
			DATE & TIME
			2/6/24 10:10

REQUESTED SERVICES (Please check the appropriate boxes)

No.	Sample ID (10 Characters Max)	Sample Description	Volume or Area	Paint Chips		Bulk (mg/kg)		Soil (mg/kg)		Wipes (ug/ft <sup>2</sup> )		Air (ug /m <sup>3</sup> )		TCLP - Pb		TCLP - RCRA 8		RCRA 8		Other	
				Wipe ppt mg/cm <sup>2</sup>	Wipe ppt mg/cm <sup>2</sup>	Wipe ppt mg/cm <sup>2</sup>	Wipe ppt mg/cm <sup>2</sup>	Wipe ppt mg/cm <sup>2</sup>	Wipe ppt mg/cm <sup>2</sup>	Wipe ppt mg/cm <sup>2</sup>	Wipe ppt mg/cm <sup>2</sup>	Wipe ppt mg/cm <sup>2</sup>	Wipe ppt mg/cm <sup>2</sup>	Wipe ppt mg/cm <sup>2</sup>	Wipe ppt mg/cm <sup>2</sup>	Wipe ppt mg/cm <sup>2</sup>	Wipe ppt mg/cm <sup>2</sup>	Wipe ppt mg/cm <sup>2</sup>	Wipe ppt mg/cm <sup>2</sup>	Wipe ppt mg/cm <sup>2</sup>	Wipe ppt mg/cm <sup>2</sup>
1	01	Kitchen Floor	144sq in	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2	02	Kitchen Window Sill	2x16 inches	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3	03	Laundry Room Floor	144 Sq In	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4	04	Laundry Room window Sill	3 x 18 inches	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5	05	Bath Room Floor	144 sq in	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6	06	Bath Room window sill	2 1/2 x 26	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7	07	Pourch Floor	144 sq in	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8	08	Drip line	45ml	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9				<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10				<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11				<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

TURNAROUND TIME

Same Day

24 - Hour

3 - Day

5 - Day

SATURDAY FEDERAL SAMPLE DELIVERY - CALL TO SCHEDULE • Use this address for Saturday Delivery only: 4220 N. Santa Fe Ave., Oklahoma City, OK 73105-8517 • Mark Package "Hold for Saturday Pickup"  
 Please Note - UPS and USPS are NOT available for Saturday Delivery

## APPENDIX C: SCOPE OF WORK/REQUEST