



# HACN HOUSING REHAB SITE DIRECTIONS

---

**Name:** Donalda Marshall

**Telephone:** (918)640-8074

**Address:** 6146 E 570 Rd  
Locust grove, OK 74352

**County:** Mayes      **Year Built:** 1970

**GPS Coordinates:** 36.190308-95.151331      **Drive Time:** 45min

---

**Directions:** From Cherokee Nation, turn left on 62 go 2mi turn right go 2mi to 82/62 jct. continue north towards locust grove turn right on e570rd across from kum&go store go approx 3/4 mi house be on right grey in color with burgandy roof.

---

Melvin Blossom

7-3-2024

---

Cost Estimator/Inspector

---

Date

# WorkWrite-Up and Bid Document/By Trade

**Donalda Marshall**

6146 E 570 Rd Locust Grove, OK 7-4352  
 (918) 640-8074

*Contractor Name:* \_\_\_\_\_

*Contractor Signature:* \_\_\_\_\_

*This document must be signed to be a valid bid.*

**PROJECT TYPE: Emergency Repairs      Bid Due Date:**

Trade	Work Description / Comments	Gen. Spec.	Qty/Unit	Item Bid
<u>Electrical</u>				
1	<b>Area: ELECTRICAL</b>  Underground Wiring/200 AMP service. Install new underground power wiring from the electric meter to house service panel. All wire shall be placed in conduit, and buried min 2' underground. Add a service disconnect at the meter.	<b>Div.# 13.D.</b> 12	125 LF	<div style="border: 1px solid black; width: 40px; height: 30px; margin: 0 auto;"></div>
<u>HVAC</u>				
2	<b>Area: HVAC</b>  HVAC Equipment Replace/ Replace existing with 3.0 Ton 16 seer ELECTRIC HEAT & COOLING. COMPLETE CHANGE OUT /INCLUDING: PLENUM, FILTER GRILL, REGISTERS, THERMOSTAT, ALL WIRING & CONDENSOR LINES. CHECK; Duct Work for Leaks & make all necessary repairs.	<b>Div.# 12</b>	1 Ea	<div style="border: 1px solid black; width: 40px; height: 30px; margin: 0 auto;"></div>

Trade	Work Description / Comments	Gen. Spec.	Qty. Unit	Item Bid
-------	-----------------------------	------------	-----------	----------

All construction shall be in accordance with local codes, manufacturers' recommended installation procedures, good quality workmanship practices, General Specifications and Lead-Based Paint requirements when applicable. Conflicts between requirements will be resolved by compliance with the more stringent requirement.

Total: