

## HACN HOUSING REHAB SITE DIRECTIONS

Name: <u>Lucille Harper</u> Telephone: (918)313-0691

Address:

331

Tulsa, OK 74106

County: Tulsa

Year Built: 1942

GPS Coordinates: 36.18817,-95.99002 Drive Time: 1 hour



**Directions:** From Cherokee Nation, HIGHWAY 82 North to Locust Grove, then Hwy 412 west to Catoosa, then stay right and Follow I-244 W toward Sand Springs continue on I-244 West 9 miles to exit 6A for Detroit Ave, exit and stay right onto MLK Blvd, then go to E Xyler St. exit right then, left onto N Cincinnati Ave, then turn right onto E Young St. go to the 14th house on the left. White house with gray roof.

Mike Dreadfulwater	4/9/24	
Cost Estimator/Inspector	Date	

## WorkWrite-Up and Bid Document/By Trade

Lucille Harper Contractor Name:		
331 East Young St. Tulsa, OK 7-4106		
(918) 313-0691 Contractor Signature:		
This document must be s	be signed to be a valid bid.	id.
PROJECT TYPE: Emergency Repairs	Bid Due Date:	
Trade Work Description / Comments Gen. Spec.	Qty Unit	Item Bid
Plumbing		
1 Area: EXTERIOR Div.# 11.A.	70 LF	
Yard Line/Sewer/PVC. Install SCh. 40/ 4" Sewer pipe with a clean out and cap.		
Install a new SCH 40/4" PVC sewer pipe from the back of the house to the Tulsa City sewer main, includes a clean-out with cap. Requires a State Licensed Plumbing		
Site Work		
2 Area: EXTERIOR Div.# 2.M	12 LF	
Fence/Replace/Repair/Install. See comments		
A small portion of the wooden plank fence will need to be removed to get a small excavator in the back yard. Contractor will be responsible for putting the fence back after		
all of the work has been completed.		
3 Area: EXTERIOR Div.# 2.F.3.	840 SF	
Yard/Grade. Grade yard/ Clean up work site. Back fill, then grade trench site, rake smooth, and remove excess rock and dirt from the site.		
Clean up the work site after the new sewer line has been installed. Grade the work site and haul exess rock and dirt to a legal dump site.		
Print Date: Wednesday, April 10, 2024  331 East Young St. Tulsa. OK 7-4106		Port 1 of 2

331 East Young St. Tulsa, OK 7-4106

Page I of 2

compliance with the more stringent requirement.