SITE DIRECTIONS HACN HOUSING REHAB




Name: Helen Mitchell

Telephone: (918)774-8419

Roland, OK 74954 D19274 S 70980I :ssənbbA

Conuty: Sequoyah Year Built: 2000

GPS Coordinates: 35.44113,-94.52022 Drive Time: Ihr 20min



mi furn right on \$ 4774 to then left on E 1086 rd go 0.1 mi house on the right east on 64 go 1/2 mi turn left on M 4780 rd go 3 mi turn right on E 1085 rd go 1/2Directions: From Cherokee Nation, From I-40 take exit 325 toward Roland turn

Date 1/16/54

Maurice Gifford 918-506-9860

Cost Estimator/Inspector

WorkWrite-Up and Bid Document/By Trade

Helen Mitchell	Contractor Name:		
108607 S 4776 Rd Roland, OK	Contractor Signature:		
	This document mu	This document must be signed to be a valid bid.	bid.
PROJ	PROJECT TYPE: Rehabilitation	Bid Due Date:	
Trade Work Description / Comments	mments Gen. Spec.	Qty Unit	Item Bid
Carpentry			
Area: LIVING ROOM #1	Div.# 8.A.	1 Ea	
Door/Exterior/6-Panel Steel/Pre-Hung/Replace. Replace exterior entrance door with new bre-hung-steel six panel door. Work shall include paint-both sides, lockset, deadbolt & beephole.	Replace exterior entrance door with new paint-both sides, lockset, deadbolt &		
Replace front door with side lights to a 36" ext door with no glass. Fram in each side to senter up door. Doe's want a door like what is in there	oor with no glass. Fram in each side to there		
Area: EXTERIOR	Div.#6.FF.	480 SF	
Flooring/Porch/2" x 6" Pressure Treated/Replace. Replace porch flooring, 2" x 6" pressure treated.	. Replace porch flooring, 2" x 6"		
Replace with 5/4 radious edge on back deck. Joist and fram is good. Replace flooring only	st and fram is good. Replace flooring		
Area: EXTERIOR	Div.#6.V.	54 LF	
Guardrail/Pressure Treated/Install. Install new guardrail, pressure treated lumber. 4" x 4" sost, 2" x 4" stringer, 2" x 6" handrail. Includes Balusters.	ıardrail, pressure treated lumber. 4" x 4" alusters.		
Replace handrails around deck. Will be 5x5 post. Remove gate homeowner does not vant a gate on it	Remove gate homeowner does not		

Trade Work Description / Comments	Gen. Spec.	Qty Unit	Item Bid
Carpentry			
4 Area: EXTERIOR	Div.# 6.KK.	14 LF	
Post/Porch/5" \times 5" Pressure Treated/Replace. Replace 5" \times 5" support post with metal	t with metal		
standoff post base.			
Add post every 8' on bottom outside of deck. Let post run on up for handrails	ils		
5 Area: EXTERIOR	Div.# 15	32 SF	
Siding/Smartboard/Install smartboard lap siding. Include matching trim & corners	orners		
On each side of front door where it is framed in for 36" door use 4x8 sheet textured smart siding includes all trim needed	textured smart		
6 Area: EXTERIOR	Div.# 8.B	1 Ea	
Storm Door/Vinyl Clad/Install. Install new storm door, vinyl clad. Use Larson model 298-SS or written approved equal.	model 298-		
Front door			
Drywall & Finish			
7 Area: INTERIOR	Div.# 9.D	32 SF	
Drywall/Wall/Install new 1/2" drywall on wall/Finish completely. Work shall include tape, bed and texture to match existing surfaces.	include tape,		
Front door area			
HVAC			
8 Area: UTILITY ROOM #1	Div.# 12	1 Ea	
HVAC Equipment/Replace Central Cooling & Nat. Gas Heating 3 TON/16 SEER HVAC System. INSIDE AND OUTSIDE EQUIPMENT/INCLUDING FURNACE /CONDENSOR/CONDENSOR LINES & AC Coil, Thermostat, and Venting.	SEER HVAC ONDENSOR/		
Size unit to sq footage of house			
Paint & Finish			

Print Date: Tuesday, July 23, 2024

108607 S 4776 Rd Roland, OK 7-4954

Page 2 of 4

Trade Work Description / Comments Gen. Spec.	Qty Unit	Item Bid
Paint & Finish		
9 Area: EXTERIOR Div.# 9.N.4	30 SF	
House/Paint/Two Coats. Paint exterior of the house (two coats). Include cleaning, caulking and filling of small holes.		
Paint around front door where it is framed in match exsisting as close as possible		
10 Area: INTERIOR Div.# 9.N.3	38 SF	
Walls/Paint walls / Two coats.		
Paint from wall to wall around front door		
Plumbing		
11 Area: UTILITY ROOM #1 Div.# 11.A	1 Ea	
Water Heater/ Natural Gas/40 Gallon. Replace water heater with a new 40 gal. Work shall include elevating to 18" (if in garage), TPR, combustion air, Gas Flex line, Flex water supply connections, and drain Pan. Code Legal Installation. Bradford White.		
Sheetmetal & Gutters		
12 Area: EXTERIOR Div.# 7.F.	28 LF	
Gutters/ Repair. Repair existing gutter/See comments.		
Replace damaged gutters with gutter gaurds on north side of house. Match exsisting		
13 Area: EXTERIOR Div.# 7.F.	2LF	
Gutters/ Repair. Repair existing gutter/See comments.		
Install valley splash shield above deck on back of house to keep water from runing off on deck		
Thermal Protection		

Trade	Work Description / Comments	Gen. Spec.	Qty Unit	Item Bid
Thermal Protection	נ			
14 Area: EXTERIOR	OR	Div.# 14	16 SF	
Insulation/Exterior V batts.	Insulation/Exterior Wall/R-13. Add R-13 insulation to exterior wall. Use R-13/kraft faced batts.	se R-13/kraft faced		
Insulate where front door is framed in	door is framed in			
15 Area: EXTERIOR	OR	Div.# 14	32 SF	
Insulation/Residenti	Insulation/Residential Sheathing Faced Polystyrene board/ Install 1x4x8 board insulation.	x8 board insulation.		
Around front door				
All construction s installation proced Based Paint requi compliance with t for conducting sa	All construction shall be in accordance with local codes, manufacturers' recommended installation procedures, good quality workmanship practices, General Specifications and Lead-Based Paint requirements when applicable. Conflicts between requirements will be resolved by compliance with the more stringent requirement. Contractor awarded the job will be responsible for conducting safe work practices that comply with OSHA Construction Standards for Asbestos	acturers' recommended eneral Specifications a requirements will be re- arded the job will be re- struction Standards for	d Ind Lead- solved by sponsible Asbestos	Total:
Workers. Asbesto attached Asbestos	Workers. Asbestos report, where required, will be attached if areas tested are 1% or greater. See attached Asbestos Sampling Report for location and testing of Planned Work Activities.	eas tested are 1% or gr Planned Work Activities	eater. See s.	