

HACN HOUSING REHAB SITE DIRECTIONS

Name: Ricky Black

Telephone: (918)856-0003

Address:

1086 N 439 Rd

Pryor, OK 74361

County: Mayes

Year Built: 2000

GPS Coordinates: 36.32347, -95.18375 Drive Time: 45 Min



Directions: From Cherokee Nation, Use GPS for Location
Take State Hwy 82 N to N 438 in Mayes County 48 min (39.4 mi) Turn left onto US-62 E/S Muskogee Ave 1.9 mi Turn right onto US-62 E 2.2 mi Continue straight onto OK-82 BYP/State Hwy 82 N Continue to follow State Hwy 82 N 32.2 mi Turn left onto OK-20 W/E Ferry St Continue to follow OK-20 W 3.1 mi Follow N 438 and E 480 to S 439 4 min (2.6 mi) Turn right onto N 438 1.5 mi Turn right onto E 480 0.9 mi Slight left to stay on E 480 0.1 mi Slight left onto S 439 292 ft 1086 S 439


Pryor, OK 74361

Rodney Carman (918) 506-9858

7/25/2024

Cost Estimator/Inspector

Date



Imagery ©2024 TerraMetrics, Map data ©2024 Google 5 mi

via State Hwy 82 N

Fastest route, the usual traffic

42.2 miles

53 min

Explore nearby 1086 S 439

17

Restaurants

0

Hotels

() à

Gas stations Parking Lots

More

WorkWrite-Up and Bid Document/By Trade

Ricky Black	Contractor Name:			
1086 N 439 Rd Pryor, OK 7-4361	Contractor Signature:			
(918) 856-0003	Thi	s document must be	This document must be signed to be a valid bid.	
	PROJECT TYPE: Emergency Repairs	pairs	Bid Due Date:	
Trade Work Description / Comments		Gen. Spec.	Qty Unit	Item Bid
Carpentry				
1 Areu: BATHROOM #1		Div.#6.M.2	16SF	
Floor/Repair. Repair floor/See comments.	S.			- ALVANORA - CONT
Remove floor in front of bathroom sink and replace	d replace			
2 Area: BATHROOM #2		Div.#6.M.2	48 SF	
Floor/Repair. Repair floor/See comments.	S			
Remove and replace with matching thickness of plywood in front of bathroom sink and shower	ess of plywood in front of bathroom	sink and		
3 Area: EXTERIOR		Div.#6.AA	152 LF	
⁼ ence/Repair fence/See comments.				
Reattach Skirting where loosa around entire dwelling	ire dwelling			
4 Area: EXTERIOR		Div.#6.FF.	192 SF	
Flooring/Porch/2" x 6" Pressure Treated/Replace. Replace porch flooring, 2" x 6" pressure treated.	Replace. Replace porch flooring, 2" >	6		

Trade Work Description / Comments Gen. Spec.	c. Qty Unit	Hem Bid
Carpentry		
5 Area: EXTERIOR Div.#6.R	R 1Ea	
Stairs/Exterior/Wood/Replace. Replace existing stairs with new exterior wood stairs/ 4' wide. Work shall include 2"X6" handrails & Balusters on each side.		
remove and rebuild steps according to stair codes		
6 Area: EXTERIOR Div.# 16.A.	6.A. 27LF	
Wheel Chair Ramp/Wood/Install 4' inside clear space wheel chair ramp/pressure treated lumber work includes balusters, handrails, guardrails, concrete landing at the end of ramp.	ted amp.	
Build to run west from edge of porch where existing starts around to east side and run south lenght needed for handi cap code 1" fall for 12" lenght	,	
Flooring		
7 Area: INTERIOR Div.#9.L	960 SF	
Flooring/ Install vinyl/waterproof/flooring planks. Install vinyl planks with 20 mil wear layer, 5.0 mil backing with 25 year residential warranty. Work shall include floor level, seal concrete, moisture resistant glue and top seal. Entire house		
8 Area: INTERIOR Div.#9.L	L 106SY	
Vinyl Flooring Remove existing vinyl flooring See comments. remove all flooring		
Plumbing		
9 Area: EXTERIOR Div.#11.A	1.A 27 Ea	
Remove item. See comments.		
remove existing handi cap ramp and dispose of properly		
Roofing		

Print Date: Thursday, July 25, 2024

1086 N 439 Rd Pryor, OK 7-4361

Page 2 of 3

Trade Work Description / Comments Gen. Spec.	. Qty Unit	it Item Bid
Roofing		
10 Area: ROOF Div.#7.A.	1. 12 Sq	
Roofing/Heritage/30 Year Warranty. Install fiberglass shingles/Minimum 30 year warranty/Lise Marlarkey/Tamko or written approved equal. 30 lb Felt. Painted Style D		
warranty/Use Mariarkey/Tamko or written approved equal. 30 ib Heit, Painted Style D. Drip Edge, Pipe Flashing, Valley Flashing, & Attic vents.		
11 Area: ROOF Div.#7.C) 12 Sq	
Roofing/Strip/Asphalt-Fiberglass. Remove all layers, and haul roofing debris to a Legal	_	
12 Area: ROOF Div.#7.B	3 256 SF	
Sheathing/Replace/Match Existing. Replace existing sheathing. Match existing as closely as possible.	sely	
Replace as needed		
All construction shall be in apportunes with local codes manufacturers' recommended	mondod	

All construction shall be in accordance with local codes, manufacturers' recommended installation procedures, good quality workmanship practices, General Specifications and Lead-Based Paint requirements when applicable. Conflicts between requirements will be resolved by compliance with the more stringent requirement.