



HACN HOUSING REHAB SITE DIRECTIONS


Name: Douglas McCarter

Telephone: (918)570-2979

Address: 17565 E Robin Dr
Tahlequah, OK 74464

County: Cherokee Year Built: 1974

GPS Coordinates: 35.97582, -94.98247 Drive Time: 20 Mins



Directions: From Cherokee Nation, Turn right on US-62 E and go 3 miles to US-62 E, turn right onto US-62 E and go 2.3 miles to Bertha Parker Bypass and continue for 1.8 miles to Hwy 82 N, continue onto Hwy 82 N for 2.5 miles to Jones Rd, turns left onto Jones Rd and go 0.8 miles to Grandview Dr, turn right onto Grandview Dr and go 0.1 miles to Robin Dr. go left onto Robin Dr. home will be the third home on the left

Scotty Woodard
Cost Estimator/Inspector

6/28/23
Date

WorkWrite-Up and Bid Document/By Trade

Douglas McCarter (HVAC)

17565 W Robin Dr Tahlequah, OK 7-4464
 (918) 570-2979

Contractor Name:

Contractor Signature:

This document must be signed to be a valid bid.

PROJECT TYPE: Emergency Repairs Bid Due Date:

Trade	Work Description / Comments	Gen. Spec.	Qty Unit	Item Bid
HVAC:				
1	<i>Area:</i> HVAC HVAC Equipment Replacement/Central Heating & Cooling 3.5 ton / Propane Gas Furnace/3.5 TON System. INCLUDES: Electrical wiring, Coil Box, new coil, Copper Lines, Condensate Line, Thermostat, Filter Grill, Condenser.	Div.# 12	1 Ea	

All construction shall be in accordance with local codes, manufacturers' recommended installation procedures, good quality workmanship practices, General Specifications and Lead-Based Paint requirements when applicable. Conflicts between requirements will be resolved by compliance with the more stringent requirement.

Total: