

HACN HOUSING REHAB SITE DIRECTIONS

Name: Robert Kirk

Telephone: (539)251-7868

Address:

51127 CR 504

Salina, OK 74365

County: Delaware

Year Built: 1998

GPS Coordinates: <u>36.27681,-94.94854</u> Drive Time: <u>50min</u>





Directions: From Cherokee Nation, From Locust Grove take US-412 Alt E. Go 9 mi turn left on Country Rd 504 in leach. Go 2.8 mi driveway will be on the left

Maurice Gifford 918-506-9860

4/15/24

Cost Estimator/Inspector

Date

WorkWrite-Up and Bid Document/By Trade

Robert Kirk Contractor Name:			
51127 Country rd 504 Salina, OK 7-4365 Contractor Signature:			
(539) 251-7868	This document must	This document must be signed to be a valid bid.	oid
PROJECT TYPE: Rehabilitation	on	Bid Due Date:	
Trade Work Description / Comments	Gen. Spec.	Qty Unit	Item Bid
Appliances 1 Area: KITCHEN	<i>Div.</i> # 10.D. 3.D	<u>→</u> m	
Vent-A-Hood/30"/Recirc./Replace. Replace existing vent-a-hood with new kitchen vent-a- hood (recirc.)/30".	kitchen vent-a-		23
Carpentry			
2 Area: KITCHEN	Div.#6.0.2	13LF	
Base Cabinets/Install/Oak. Install new base cabinets/pre-finished oak.			
They are no exsisting		Agençia diskining and a second of trementary and a second of the second	
3 Area: KITCHEN	Div.# 6.0.4.	15 LF	
Countertop/New/Post Form Top. Install new countertop and backsplash.			
4 Area: EXTERIOR	Div.#8.A.	3 Ea	
Door/Exterior/Half-Glass/Pre-Hung Steel/Replace. Replace exterior entrance door with new pre-hung-steel two panel with 1/2 glass. Work shall include paint-both sides, lockset, deadbolf & neephole	ce door with sides, lockset,		periodical de la companya del companya del companya de la companya

Trade Work Description / Comments	Gen. Spec.	Qty Unit	Item Bid
Carpentry		İ	
5 Area: KITCHEN	Div.# 10.G	ETT BD	
Fire Extinguisher/Install. Install new fire extinguisher.			
6 Area: EXTERIOR	Div.# 16.A.	35 LF	
Handrails/Wood/Install Handrails. Install new rails on both sides. Use treated lumber.	e treated lumber.		
Around front porch			
7 Area: EXTERIOR	Div.# 15	300 SF	
Siding/Smartboard/Install smartboard lap siding. Include matching trim & corners	im & corners		
Replace all vynal siding with lap siding match exsisting			
8 Area: EXTERIOR	Div.#8.B	3 Ea	
Storm Door∕Vinyl Clad/Install. Install new storm door, vinyl clad.Use Larson model 298- SS or written approved equal.	Larson model 298-		
9 Area: KITCHEN	Div.#6.0.2	17 LF	
Wall Hung Cabinets/Pre-Finished Oak. Install new wall hung cabinets (pre-finished oak).	ts (pre-finished oak).		
They are no exsisting			
10 Area: EXTERIOR	Div.# 16.A.	34 LF	
Wheel Chair Ramp/Wood/Install 4' inside clear space wheel chair ramp/pressure treated lumber work includes balusters, handrails, guardrails, concrete landing at the end of	mp/pressure treated ng at the end of		
ramp.			
Will include 2 switchbacks. Come on deck in Horit of Horit door	2.	0 10	
11 Area: EXTERIOR	Div.#8.G	9 Ha	* ************************************
Window/Replace/Vinyl Thermopane/Low-E Replacement window,with Grids,Locks,and Tilt window for cleaning. White Vinyl, American Craftsman Series, or written approved egual. Includes frame, sill, sash, trim, hardware, screen.	th Grids,Locks,and r written approved		

Page 3 of 4		Print Date: Tuesday, April 16, 2024 51127 Country rd 504 Salina, OK 7-4365
ACCOUNTS AND AND	1600 SF	Site Work 16 Area: EXTERIOR Termites-Wood Destroying Insects/Treat Structure. Treat structure for wood destroying insects. Use state licensed applicator.
GISTON OF CO.	n m	Plumbing Div.# 11.A 15 Area: KITCHEN Div.# 11.A Sink & Faucet/Kitchen. Install new stainless steel kitchen sink (33" x 22" x 7") & Faucet (Use Delta single-handle model100-WF or written approved equal). Work shall include new drain lines, trap and shutoffs (2).
PARAMETER CONTROL	2500 SF	Paint & Finish 14 Area: ENTIRE STRUCTURE House/Paint/Two Coats. Paint exterior of the house (two coats). Include cleaning, caulking and filling of small holes.
	Д Ш	13 Area: HVAC 13 Area: HVAC HVAC Equipment Replace/ Replace existing with 3.0 Ton 16 seer ELECTRIC HEAT & COOLING. COMPLETE CHANGE OUT /INCLUDING: PLENUM, FILTER GRILL, REGISTERS, THERMOSTAT, ALL WIRING & CONDENSOR LINES. CHECK; Duct Work for Leaks & make all neccessary repairs. Size unit to sq footage of house
	4 E	12 Area: HALLWAY #1 12 Area: HALLWAY #1 13.D. 11 Smoke Detector/Battery Operated/Install new smoke detector, battery operated (10 year lithium battery). All bedrooms and hallways adjacent to bedrooms. Use Firex #4015 or written approved equal.
Item Bid	Qty Unit	Trade Work Description / Comments Gen. Spec.

THE REAL PROPERTY AND PERSONS ASSESSMENT OF THE PERSONS ASSESSMENT OF			
		attic over air conditioned & heated spaces.	attic over
Curt		Insulation/Add/Attic/R-19. Add R-19 Pink Blown-in fiberglass Insulation in attic. Entire	Insulation
	100000	17 Area: ATTIC Div.# 14	17 Are
		Thermal Protection	Thermal
Item Bid	Qty Unit	Work Description / Comments Gen. Spec.	Trade

for conducting safe work practices that comply with OSHA Construction Standards for Asbestos attached Asbestos Sampling Report for location and testing of Planned Work Activities. Workers. Asbestos report, where required, will be attached if areas tested are 1% or greater. See compliance with the more stringent requirement. Contractor awarded the job will be responsible Based Paint requirements when applicable. Conflicts between requirements will be resolved by installation procedures, good quality workmanship practices, General Specifications and Lead-All construction shall be in accordance with local codes, manufacturers' recommended