

HACN HOUSING REHAB SITE DIRECTIONS

Name: <u>James Goard</u> Telephone: (918)871-9849

Address:

8020 W 710 rd

Hulbert, OK 74441

County: Cherokee

Year Built: 1971

GPS Coordinates: <u>35.98813,-95.15364</u> Drive Time: <u>28min</u>





Directions: From Cherokee Nation, From Hulbert go N on N Birch st/Lost City rd go 4 mi turn left on W 710 rd go 0.9 mi house is on the left

Maurice Gifford 918-506-9860

7/1/24

Cost Estimator/Inspector

Date

WorkWrite-Up and Bid Document/By Trade

Page 1 of 7		8020 W 710 rd Hulbert, OK 7-4441	Print Date: Tuesday, July 2, 2024
		Door/Exterior/6-Panel Steel/Pre-Hung/Replace. Replace exterior entrance door with new pre-hung-steel six panel door. Work shall include paint-both sides, lockset, deadbolt & peephole.	Door/Exterior/6-Panel Steel/Pre-Hung/Repre-hung-steel six panel door. Work shal peephole.
	2 Ea	Div.#8.A.	4 Area: EXTERIOR
		Base Trim/Pine, K- Pattern 2-1/4" Solid/ Stain Grade /Replace. Replace base trim, K-Trim, solid pine,2-1/4". Stain & Finish.	Base Trim/Pine, K- Pattern 2-1/4" Solid/ Trim, solid pine,2-1/4". Stain & Finish.
	30 LF	Div.#6.N	3 Area: BATHROOM #1
			Carpentry
		Refrigerator/Top Freezer/Energy Star/20.2 C.F. Mimium Size/Replace. Replace existing refrigerator with new 20.2 C.F. (minimum size) refrigerator with top freezer. Must be Energy Star compliant.	Refrigerator/Top Freezer/Energy Star/20 refrigerator with new 20.2 C.F. (minimum Energy Star compliant.
	1Ea	Div.# 10.F	2 Area: KITCHEN
		Oven/Range/Gas/30"/ 4 Burner Free Standing. Replace existing oven with new 30" free standing gas range/oven with clock, oven window and supply lines, shutoff valve and one-year manufacturer's warranty.	Oven/Range/Gas/30"/ 4 Burner Free Sta standing gas range/oven with clock, over year manufacturer's warranty.
	1 Ea	<i>Div.</i> # 10.F	1 Area: KITCHEN
			Appliances
Item Bid	Qty Unit	Work Description / Comments Gen. Spec.	Trade Work Descripti
	Bid Due Date:	PROJECT TYPE: Rehabilitation	
bid.	This document must be signed to be a valid bid.	This document must	(010) 071-00-0
		Contractor Signature:	8020 W 710 rd Hulbert, OK 7-4441
		Contractor Name:	James Gourd

Trade Work Description / Comments	Gen. Spec.	Oty Unit	Item Bid
Drywall & Finish			
11 Area: BATHROOM #1	Div.# 9.D	96 SF	
Drywall/Moisture Resistant/Replace. Replace existing drywall with new moisture resistant drywall- 1/2". Interior Drywall or written approved equal.	noisture		
Where shower is replaced and patch any sheetrock needed. Remove vynal base and skim with mud	nal base and		
Electrical			
12 Area: HALLWAY #1	<i>Div.</i> # 13.D.	а Ш	
Carbon Monoxide Detector/Direct Plug Type/Install. Install a new direct plug type carbon monoxide detector.	lug type carbon		
13 Area: INTERIOR	<i>Div.</i> # 13.D. 9.B	5 Ea	
Ceiling Fan, Light Kit /52"/Install new ceiling fan with light kit.			
living room and 4 bedrooms			
14 Area: ENTIRE STRUCTURE	<i>Div.</i> # 13.D.	24 Ea	
Cover Plate/Outlet/Install new outlet/ cover plate.			
15 Area: UTILITY ROOM #1	<i>Div.</i> # 13.D.	1 Ea	
Fixure/Pull Chain/Replace pull chain fixture.			
Above washer and dryer			

Trade	Work Description / Comments	Gen. Spec.	Qty Unit	Item Bid
Electrical				
16 Area: BATHROOM #1	W #1	Div.# 13	1 Ea	
Light Fixture/Bathroom/3 Light/Replace. Light/Globe, wall mounted light fixture.	/3 Light/Replace. Replace existing light fixture with new 3 ted light fixture.	new 3		
3 bulb bar light fixture				
17 Area: BATHROOM #1	N #1	<i>Div.</i> # 13.D.	1 Ea	
ewitch	Light Fixture/Vent-Light/Install new bathroom light (100 watt), vent fan (70 CFM) and	FM) and		
Includes all wiring and s	Includes all wiring and switch for complete install. Install over shower area			
18 Area: BATHROOM #1	A #1	<i>Div.</i> # 13.D.	1 Ea	
Outlet/GFCI/Replace ex possible to panel box to	Outlet/GFCI/Replace existing outlet with new GFCI outlet. Place GFCI as close as possible to panel box to protect downstream outlets. One GFCI per circuit.	ose as		
19 Area: KITCHEN		<i>Div.</i> # 13.D. 6.	1Ea	
Outlet/GFCI/Replace ex possible to panel box to	Outlet/GFCI/Replace existing outlet with new GFCI outlet. Place GFCI as close as possible to panel box to protect downstream outlets. One GFCI per circuit.	ose as		
20 Area: KITCHEN		Div.# 13	1 Ea	
Panel Box/Repair. See comments.	comments.			
Needs panel box cover				

Trade Work Description / Comments Gen. Spec.	Qty Unit Ites	Item Bid
Electrical		
21 Area: INTERIOR Div.# 13.D.	5Ea	
Smoke Detector/Battery Operated/Install new smoke detector, battery operated (10 year lithium battery). All bedrooms and hallways adjacent to bedrooms. Use Firex #4015 or written approved equal. Hallway and 4 bedrooms	Г	l
22 Area: INTERIOR Div # 13 D	n	
Switch & Circuit Wiring/3-Way/Install new 3-way switch, cover plate and circuit wiring.		
Replace exsisting in hallway, kitchen and living room		
23 Area: ENTIRE STRUCTURE Div.# 13.D. 1	12 Ea	
Switch & Cover Plate/20 Amp/Replace switch and cover/20 amp.		
Flooring		
24 Area: BATHROOM #1 Div.# 9.E. 5	50 SF	
VCT Tile/Replace VCT tile/See comments.		
Remove old and replace with new		
HVAC		
25 Area: LIVING ROOM #1 Div.# 12.C.	1 Ea	
Wood Stove Flue Kit/Install New 8" Triple Wall Flue Kit /Metal Fab Pipe /Verticle Twist locking flue pipe, Ceiling box, Roof Jack 3/12 - 6/12 pitch, Chimney Cap, Pipe Collar.	Г	
Paint & Finish		

Trade Work Description / Comments Gen. Spec.	Qty Unit	Item Bid
Paint & Finish		
26 Area: BATHROOM #1 Div.# 9.N.3	250 SF	
Paint Interior /Ceilings, Walls, & Trim /Paint Two coats, . Work shall include minor repairs to surfaces. SF=ACTUAL SURFACE AREA OF WALLS & CEILING.		
27 Area: ENTIRE STRUCTURE Div.# 9.N.4	1600 SF	
House/Paint/Two Coats. Paint exterior of the house (two coats). Include cleaning, caulking and filling of small holes.		
Plumbing		
28 Area: BATHROOM #1 Div.# 16.C.	1 Ea	
Commode/High Rise/Handicap /Replace commode with new high rise/Handicap commode with Seat & two (2) grab bars. include new shutoff, supply line and wax ring. Examine condition of the flange and report if damaged. Consult owner for location of grab bars		
29 Area: EXTERIOR Div.# 11.A	1 Ea	
Freezeless, anti-Siphon Hose bib. Replace exterior hose bib with new a 1/2" \times 8" - 12" Freezeless hose bib with vacuum breaker.		
Hydrant has been removed and capped off in bathroom wall install new one and access panel		
30 Area: BATHROOM #1 Div.# 16.C. Lavatory Sink & Faucet/ADA/Wall Hung. Install new wall hung lavatory sink supply lines	1 En	
Lavatory Sink & Faucet/ADA/Wall Hung. Install new wall hung lavatory sink supply lines, drain lines, shutoffs, escutcheon plates, insulation for all water and drainlines. Use Orion #52000020 sink, Delta model 520-WFMPU faucet or written approved equal.		

Trade	Work Description / Comments	Gen. Spec.	Qty Unit	Item Bid
Plumbing				
31 Area: BATHROOM #1		Div.# 16.C.	1 Ea	
Shower/Handicap/Pre-Fab/li	Shower/Handicap/Pre-Fab/Install new 34" x 60" x 74" /Pre-fab 3 or 4 piece/60" x 34" x)/60" x 34" x		
74" with 3-grab bars, fold down shower se glide bar. Includes all necessary Plumbing.	74" with 3-grab bars, fold down shower seat, and pressure balanced shower valve with glide bar. Includes all necessary Plumbing.	ver valve with		
Use portable shower seat in	Use portable shower seat includes all plumbing and drain lines and any concrete work	ncrete work		
Site Work				
32 Area: ENTIRE STRUCTURE	TURE	Div.# 2.Q	1200 SF	
Pests/Treat Structure. Treat Use a Oklahoma State Licer	Pests/Treat Structure. Treat structure for pests, including spiders, ants, and cockroaches. Use a Oklahoma State Licensed Applicator. Provide treatment information at completion	nd cockroaches.		

attached Asbestos Sampling Report for location and testing of Planned Work Activities. Workers. Asbestos report, where required, will be attached if areas tested are 1% or greater. See for conducting safe work practices that comply with OSHA Construction Standards for Asbestos compliance with the more stringent requirement. Contractor awarded the job will be responsible Based Paint requirements when applicable. Conflicts between requirements will be resolved by installation procedures, good quality workmanship practices, General Specifications and Lead-All construction shall be in accordance with local codes, manufacturers' recommended