

## HACN HOUSING REHAB SITE DIRECTIONS

Keys to a brighter future

Name: Robert Leeds

Telephone: (918)809-7745

Address:

30456 A Street

Catoosa, OK 74015

County: Tulsa

Year Built: 1961

GPS Coordinates: <u>36.16754,-95,68113</u> Drive Time: <u>1-hour</u>



**Directions:** From Cherokee Nation, HIGHWAY 82 North to Locust Grove, then Cherokee Turnpike 412 West 30 miles then, turn right onto 265<sup>th</sup> Ave, then right onto E 586 Rd., then left onto A St. and go to the 2<sup>nd</sup> house on the left.,

Mike Dreadfulwater	7/19/24	
Cost Estimator/Inspector	Date	

## WorkWrite-Up and Bid Document/By Trade

Page 1 of 5		30456 A St. Catoosa, OK 7-4015		Print Date: Thursday, January 30, 2025
		s and painting.	Back door; replace; match size and swing: includes all trim, locks and painting	Back door; replace; match s
[		ling glass patio door with shall include paint-both	French Patio Door/5' 0" $\times$ 6' 8"/Double Glazed/Steel. Replace sliding glass patio door with new French patio door/steel 5' 0" $\times$ 6' 8"/insulated glazing. Work shall include paint-both sides, lockset & deadbolt.	French Patio Door/5' 0" x 6' new French patio door/steel sides, lockset & deadbolt.
	1Ea	<i>Div.</i> # 8.A.1.		3 Area: EXTERIOR
		m, locks and	Replace the front door, match the size and swing; includes all trim, locks and painting. Use a low threshold for wheelchair access.	Replace the front door, match the size and swing; i painting. Use a low threshold for wheelchair access
		e. Replace exterior paint-both sides,	Door/Exterior/Fan Light Faced/Pre-Hung Metal Insulated/Replace. Replace exterior entrance door with new pre-hung steel, door. Work shall include paint-both sides, lockset, deadbolt & peephole.	Door/Exterior/Fan Light Face entrance door with new pre-h lockset, deadbolt & peephole
	1 Ea	Div.# 8.A.		2 Area: EXTERIOR
		e 2"x 8" beam placed on	Lift and level the kitchen and entrance area hallway, use a double 2"x 8" beam placed on concrete piers and cement blocks to hold the floor in place.	Lift and level the kitchen and concrete piers and cement be
		st, concrete block piers tabilize the Floor.	Level /Floor: Place Double 2"x 8" girder beams beneath floor joist, concrete block piers placed on 18" x 18"x 4" concrete pads placed 8' O/C to lift and Stabilize the Floor.	Level /Floor: Place Double 2 placed on 18" x 18"x 4" cond
	20 LF	Div.# 6.M.2		1 Area: KITCHEN
				Carpentry
Item Bid	Qty Unit	Gen. Spec.	Work Description / Comments	Trade H
	Bid Due Date:	Rehabilitation	PROJECT TYPE: Re	
bid.	This document must be signed to be a valid bid.	This document must l		
		ignature:	7-4015 Contractor Signature:	30456 A St. Catoosa, OK (918) 809-7745
		r Name:	ehab Contractor Name:	Robert Leeds Tribal Rehab

Trade Work Description / Comments	Gen. Spec.	Qty Unit	Item Bid
Carpentry			
4 Area: EXTERIOR	Div.# 8.B	1Ea	
Storm Door/Aluminum/white finish/ heavy duty Replace. Replace storm/screen door with new aluminum 1 1/4" thick storm door with a retractable screen /white finish Larson Platinum Series. Including all hardware.	en door with Larson		
Replace the storm door with a Heavy duty door.			
Drywall & Finish			
5 Area: BATHROOM #1	Div.# 9.D	32 SF	
Drywall/Moisture Resistant/Replace. Replace existing drywall with new moisture resistant drywall- 1/2". Interior Drywall or written approved equal.	ture		
Replace the drywall that at the bathroom walls where the new shower was installed, includes; mud, tape, finish and paint.	stalled,		
6 Area: INTERIOR	Div.# 9.D	128 SF	
Drywall/Wall/Replace 1/2" drywall on wall/Finish completely. Work shall include tape,bed,texture and paint to match existing surfaces.	de		
After lifting the the floor, make repairs to the sheetrock in the entrance hallway and at the ceiling in the hallways and walls throughout the kitchen and hallway area	ay and at the		
Electrical			
7 Area: HALLWAY #1	Div.# 13.D.	1Ea	
Carbon Monoxide Detector/Direct Plug Type/Install. Install a new direct plug type carbon monoxide detector.	type carbon		
Install in the hallway area.			

Qty Unit	Item Bid
1 Ea	
4 Ea	
42 SF	
488 SF	
	1 Ea 4 Ea 42 SF 42 SF

Trade Work Description / Comments Ge	Gen. Spec.	Qty Unit Item Bid	Bid
Flooring			
12 Area: BATHROOM #1	Div.# 6.F	4 SY	
Underlayment/3/8". Replace existing underlayment with new 3/8" underlayment	nt.		
Install a smooth underlayment before installing the new viyl flooring. Nail down acorrding to the manufactures recommendations to prevent warp.	acorrding		
13 Area: INTERIOR	Div.# 6.F	54 SY	
Underlayment/3/8". Replace existing underlayment with new 3/8" underlayment.	nt.		
Install a smooth underlayment before installing the new vinyl planks. Fasten the underlayment according to the manufactures instructions to prevent warp.	O	ı	
Paint & Finish			
14 Area: BATHROOM #1	Div.# 9.N.3 2	210 SF	
Paint Interior /Ceilings, Walls, & Trim /Paint Two coats, . Work shall include minor repairs to surfaces. SF=ACTUAL SURFACE AREA OF WALLS & CEILING.	inor	Г	
Paint the entire bathroom after the shower installaion. Walls & ceiling.			
Plumbing			
15 Area: BATHROOM #1	Div.# 16.C.	1 Ea	
Commode/High Rise/Handicap /Replace commode with new high rise/Handicap commode with Seat & two (2) grab bars. include new shutoff, supply line and wax ring.	wax ring.		
Examine condition of the flange and report if damaged. Consult owner for location of grab bars	tion of		
Install a Handicap High rise stool, check the stool flange before installing the new unit.	ew unit.		

Trade Work Description / Comments Gen. Spec.	Qty Unit	Item Bid
Plumbing		
<b>16</b> Area: <b>BATHROOM #1</b> Div.# 16.C.	1 Ea	
Shower/Handicap/Pre-Fab /4 piece/Install $32" \times 60" \times 77"$ Shower, with 3-grab bars, fold down shower seat, and pressure balanced shower valve with glide bar. Locke 4 piece #A1117. Delta fixtures. Hand held shower head with shut off.		
Remove the existing tub/shower unit and install a Handicap Shower Stall; includes all plumbing required for a complete system, and must have grab bars attached (3).		
Site Work		
<b>17</b> <i>Area:</i> <b>FOUNDATION</b> <i>Div.</i> # 2.Q 15	1560 SF	
Termites-Wood Destroying Insects/Treat Structure. Treat structure for wood destroying insects. Use state licensed applicator.		
Treat unit for termite control and prevention. This is a wood floor structure with a crawlspace.		
Thermal Protection		
18 Area: ATTIC Div.# 14 11	1180 SF	
Insulation/Add/Attic/R-19. Add R-19 Pink Blown-in fiberglass Insulation in attic. Entire attic over air conditioned & heated spaces.		
Add blown in insulation over all of the lived in portions of the house.		
All construction shall be in accordance with local codes, manufacturers' recommended installation procedures, good quality workmanship practices, General Specifications and Lead-Based Paint requirements when applicable. Conflicts between requirements will be resolved by compliance with the more stringent requirement. Contractor awarded the job will be responsible for conducting safe work practices that comply with OSHA Construction Standards for Asbestos Workers. Asbestos report, where required, will be attached if areas tested are 1% or greater. See	d Lead- olved by ponsible Asbestos	
attached Asbestos Sampling Report for location and testing of Planned Work Activities.	Oee	