

Tommy Tubbs 918 565 2103
Cost Estimator/Inspector

HACN HOUSING REHAB SITE DIRECTIONS

Name: <u>lee henderson</u> Telephone: <u>(918)931-5949</u>					
Address: 22097 east 572 rd colcord, OK 74338					
County: delaware Year Built:					
GPS Coordinates: <u>36.18685,-94.61728</u> Drive Time: <u>1 hr</u>					
Directions: From Cherokee Nation, Head north on US-62 E/S Muskogee Ave 1.8 miTurn right onto US-62 E2.2 mi Turn right to stay on US-62 E 1.9 mi					
Turn left onto OK-10 N 25.5 mi					
At the traffic circle, take the 1st exit onto US-59 S/Tulsa Ave Continue to follow US-59 S 9.6 mi					
Turn left onto N4710 Rd/N White Oak Rd 0.5 miTurn right onto E 572 Rd 486 ft					
22097 E 572 Rd Colcord, OK 74338					

Date

WorkWrite-Up and Bid Document/By Trade

	1	The state of the s	inc	
Lee Henderson 22097 east 572 rd colcord, Ok (918) 931-5949	Contractor Na 7-4338 Contractor Signat	ure:		
		This document mu	st be signed to be a val	lid bid.
PROJECT TYPE: Emergency Repairs			Bid Due Date:	
Trade Work	Description / Comments	Gen. Spec.	Qty Unit	Item Bid
Roofing				
1 Area: ENTIRE STRUCTURE		Div.#7.B.	1300 SF	
Add Screws/Metal Roof Repair/Apply Screws. Repair by applying Screws				
replace all screws and reseal all		0110		
installation procedures, good	cordance with local codes, manuf quality workmanship practices, G en applicable. Conflicts between	eneral Specifications	and Lead-	al: