


Memorandum

To: **George Hubbard, Housing Rehab**
CC: **Nancy John, Director, Environmental Programs**
From: **Shaun West, Environmental Specialist III**
Date: **11/18/2008**
Re: **Juliana Dotson**



Enclosed is the LBP Clearance test for Juliana Dotson (Braggs). Since all lead-based paint hazards have been corrected, the home now meets the criteria established by HUD for lead safety.

If you have any questions, please call me at 453-5363.

CONFIDENTIAL

Lead Hazard Control Visual Clearance Form

Date 11/18/08

Name of Clearance Examiner Shaun West

License Number OKRASR11453, CNRASR00001

Name of Property Owner Juliana Dotson

Property Address PO Box 233 Braggs, Ok. 74423

Date Cleanup Completed 11/13/08

Time Cleanup Completed 9:00 am

Abatement/Interim Control Contractor Name Rycon E & C Inc

Address 213 River St. Commerce, Ok. 74339

Telephone No. (918) 675-5604

Check if repeat clearance examination

Room ID	Building components requiring treatment	Work completed? (yes or no)	Paint Chips? (yes or no)	Dust? (yes or no)	Additional Work Required?
Ext.	A Wall	Yes	No	No	No
Ext	A Door	Yes	No	No	No
Ext	A Porch Ceil	Yes	No	No	No
Ext	A Porch Head	Yes	No	No	No
Ext	B Corner Lft	Yes	No	No	No
Ext	B Corner Rgt	Yes	No	No	No
Ext	C Wall	Yes	No	No	No
Ext	C Soffit	Yes	No	No	No
Ext	D Wall	Yes	No	No	No
Rm 3 Bed	B Window	Yes	No	No	No
Rm 3 Bed	C Window	Yes	No	No	No
Rm 6 Porch	A Wall	Yes	No	No	No
Rm 6 Porch	A Door	Yes	No	No	No
Rm 7 Porch	B Wall	Yes	No	No	No

Exterior Soil

Treated

Not Treated

If treated, is bare soil present

Yes

No

Was contaminated soil removed?

Yes

No

Is additional soil treatment required?

Yes

No

Signature

Stanley 01425211453

Lead Hazard Control Dust Sampling Form

Date 11/18/08

Name of Clearance Examiner Shaun West

License Number OKRASR11453, CNRASR00001

Name of Property Owner Juliana Dotson

Property Address PO Box 233 Braggs, Ok. 74423

Clearance Categories:

1. Interior treatments without containment.
2. Interior treatments with containment.
3. Exterior work on painted surfaces.
4. Routine maintenance.
5. Soil work.

Sample Number	Room Identifier	Surface Type	Clearance Category	Dimensions of Sample	Result of Lab Analysis ($\mu\text{g}/\text{ft}^2$)	Pass or Fail
1	Bed	Floor	2	12 x 12	<16.00	Pass
2	Bed	Win Sill	2	6 x 8	< 48.00	Pass
3	Bath	Floor	2	12 x 12	< 16.00	Pass
4	Bath	Win Sill	2	6 x 8	< 48.00	Pass
5	En Porch	Floor	2	12 x 12	< 16.00	Pass
6	En Porch	Win Sill	2	6 x 8	< 48.80	Pass
7	Ext	Win Sill	2	1 1/2 x 24	< 64.00	Pass
8	Ext	Floor	2	12 x 12	70.38	Pass

Total Number of Samples on this Page 8

Page 1 of 1

Date of Sample Collection 11/14/08 Date Shipped to Lab 11/14/08

Shipped by Shaun West Received by B. Holder
 (Signature) (Signature)

Lead Hazard Control Clearance Soil Sampling Form

Date 11/18/08

Name of Clearance Examiner Shaun West

License Number OKRASR11453, CNRASR00001

Name of Property Owner Juliana Dotson

Property Address PO BOX 233 Braggs, Ok. 74423

Sample Number	Location	Bare or Covered	Lab Result ($\mu\text{g/g}$)	Pass or Fail
09	Ext. Drip	Bare	142.47	Pass

Total Number of Samples on this Page 1

Page 1 of 1

Date of Sample Collection 11/14/08 Date Shipped to 11/14/08

Shipped by Shaun West Received by B. Holder
(Signature) (Signature)