

HACN HOUSING REHAB SITE DIRECTIONS

Name: Georgia Hayes Telephone: (918)408-8564


Address:

521 N 93RD E Ave Tulsa, OK 74115

County: TULSA

Year Built: 2001

GPS Coordinates: <u>36.16510 95.87255</u> Drive Time: ___



Directions: From Cherokee Nation, Get on US-412 W/Cherokee Turnpike in Locust Grove from State Hwy 82 N 28 min (24.6 mi)
Continue on US-412 W to Tulsa. Take exit 14 from I-244 W/US-412 W 36 min (39.3 mi)
Continue on N Garnett Rd. Take E Admiral Pl and N Mingo Rd to N 93rd E Ave 6 min (2.2 mi)
521 N 93rd E Ave Tulsa, OK 74115

RAY GIPSON 918/883/5850

3/12/2024

Cost Estimator/Inspector

Date



WorkWrite-Up and Bid Document/By Trade

Georgia Hayes	Contractor Name:		
ve Tulsa, OK 7-4115	Contractor Signature:		
	This document m	This document must be signed to be a valid bid.	bid.
PROJECT	PROJECT TYPE: Rehabilitation	Bid Due Date:	
Trade Work Description / Comments	ents Gen. Spec.	Qty Unit	Item Bid
Electrical			
1 Area: BATHROOM #1	<i>Di</i> v.#13.D. 16.	m m	
Vent Fan/Remove & Replace existing vent fan.			
Flooring			
2 Area: BATHROOM #1	<i>Div.</i> #9.L	4SY	
Vinyl Sheet Flooring/Install new vinyl floor (sheet) covering & shoe mold. Minimum 12 mil wear layer and 10 year manufacturer year warranty.	/ering & shoe mold. Minimum 12 mil		
Plumbing			
3 Area: BATHROOM #1	Div.# 16.C.	1 E a	
Commode/High Rise/Handicap /Replace commode with new high rise/Handicap commode with Seat & two (2) grab bars. include new shutoff, supply line and wax ring. Examine condition of the flange and report if damaged. Consult owner for location of grab	ith new high rise/Handicap w shutoff, supply line and wax ring. d. Consult owner for location of grab		

Trade Work Description / Comments	Gen. Spec.	Qty Unit	Item Bid
Plumbing			
4 Area: BATHROOM #1	Div.# 16.C.	Ea	
Shower/Elderly/Pre-Fab Install new elderly shower/Pre-fab 3 or 4 piece / with 3-grab bars, Includes a pressure balanced shower valve, glide bar,shower head, drian and with a molded in seat	3-grab an and with		n de la constantina della cons

attached Asbestos Sampling Report for location and testing of Planned Work Activities. compliance with the more stringent requirement. Contractor awarded the job will be responsible All construction shall be in accordance with local codes, manufacturers' recommended Workers. Asbestos report, where required, will be attached if areas tested are 1% or greater. See for conducting safe work practices that comply with OSHA Construction Standards for Asbestos Based Paint requirements when applicable. Conflicts between requirements will be resolved by installation procedures, good quality workmanship practices, General Specifications and Lead-