## Lead Hazard Control Visual Clearance Form

Date07/31/08
Name of Clearance ExaminerShaun West
License Number OKRASR11453, CNRASR00001
Name of Property OwnerCarmanleeta Teehee
Property Address1408 N. Joplin Tulsa, Ok. 74115
Date Cleanup Completed07/29/08
Time Cleanup Completed1:00 pm
Abatement/Interim Control Contractor NameCherokee Nation Housing Rehab_
Address PO BOX 948 Tahlequah, Ok. 74464
Telephone No. (918) 822-2785 Frank McCully
Check if repeat clearance examination

Room ID	Building components requiring treatment	Work completed? (yes or no)	Paint Chips? (yes or no)	Dust? (yes or no)	Additional Work Required?
Exterior	A Garage Door	Yes	No	No	No
Exterior	A Garage Casing	Yes	No	No	No
	2		* *	3.5	3.7

B Corner Board Yes No No No Exterior C Corner Board Yes No No No Exterior No No No C Soffit Yes Exterior No No Exterior D Corner Board Yes No

Exterior Soil	Treated	Not Treated
If treated, is bare soil present	Yes	No
Was contaminated soil removed?	Yes	No
Is additional soil treatment required?	Yes	No
Signature manh	105	

## **Lead Hazard Control Dust Sampling Form**

Date 07/31/08	
Name of Clearance Examiner Shaun West	
License Number OKRASR11453, CNRASR00001	
Name of Property Owner Carmanleeta Teehee	
Property Address 1408 N. Joplin Tulsa, Ok. 74115	
Clearance Categories:	

- 1. Interior treatments without containment.
- 2. Interior treatments with containment.
- 3. Exterior work on painted surfaces.
- 4. Routine maintenance.
- 5. Soil work.

Sample Number	Room Identifier	Surface Type	Clearance Category	Dimensions of Sample	Result of Lab Analysis (µg/ft²)	Pass or Fail
01	Exterior	A Floor	3	12 x 12	< 16.00	Pass
02	Exterior	B Win Sill	3	2 ½ x 12	<76.19	Pass
04	Exterior	C Floor	3	12 x 12	<16.00	Pass

Total Number	of Samples on this Page	3
Page1	of _L	
Date of Samp	le Collection 7/29/08	Date Shipped to Lab 7/29/08
Shipped by	Shaun West (Signature)	Received by Barbara Holder (Signature)

## Lead Hazard Control Clearance Soil Sampling Form

Date07/31/08	}			
Name of Clearance	Examiner <u>Shaun West</u>			
License Number(	OKRASR11453, CNRASE	R00001		
Name of Property C	wnerCarmanleeta Te	ehee		
Property Address	1408 N. Joplin Tulsa, (	Ok. 74115		
Sample Number	Location	Bare or Covered	Lab Result (μg/g)	Pass or Fail
03	Ext. Drip	Bare	76.61	Pass
Total Number of Sa	mples on this Page			
	-			
Page 1 of	1			
Date of Sample Col	lection 7/29/08	Date Shipped to I	ab 7/29/08	
				NOCOCOCA ASSOCIATION CONTRACTOR C
Shipped by Shaun (Signature)	West Rec	ceived by Barbara Ho (Signature)	older	