

Lead Hazard Control Visual Clearance Form

Date 3/11/13

Name of Clearance Examiner Ashley Wagnon

License Number OKRASR13320, CNRASR00018

Name of Property Owner Betty Standlee

Property Address 28472 S. 4340 Rd. Vinita, OK 74301

Date Cleanup Completed 3/11/2013

Time Cleanup Completed 10:32 AM

Abatement/Interim Control Contractor Name CN Force Account LBP Crew

Address PO Box 948, Tahlequah, OK 74465

Telephone No. 918-453-5660

Check in repeat clearance examination _____

| Room ID | Building components requiring treatment | Work completed? (yes or no) | Paint Chips? (yes or no) | Dust? (yes or no) | Additional Work Required? |
|----------|---|-----------------------------|--------------------------|-------------------|---------------------------|
| Exterior | A side Rafter | Yes | No | No | No |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |

Exterior Soil _____ Treated X Not Treated

If treated, is bare soil present _____ Yes _____ No

Was contaminated soil removed? _____ Yes _____ No

Is additional soil treatment required? _____ Yes _____ No

Signature _____

Lead Hazard Control Dust Sampling Form

Date 3/11/13

Name of Clearance Examiner Ashley Wagon

License Number OKRASR13320, CNRASR00018

Name of Property Owner Betty Standlee

Property Address 28472 S. 4340 Rd. Vinita, OK 74301

Clearance Categories:

1. Interior treatments without containment.
2. Interior treatments with containment.
3. Exterior work on painted surfaces.
4. Routine maintenance.
5. Soil work.

| Sample Number | Room Identifier | Surface Type | Clearance Category | Area of Sample | Result of Lab Analysis ($\mu\text{g}/\text{ft}^2$) | Pass or Fail |
|---------------|-------------------|--------------|--------------------|---------------------|--|--------------|
| 01 | Exterior Concrete | Floor | 3 | 144 in ² | 190 | Pass |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |

Total Number of Samples on this Page 1

Page 1 of 1

Date of Sample Collection 3/11/13

Date Shipped to Lab 3/12/13

Shipped by Ashley Wagon
(Signature)

Received by EMSL Analytical, Inc
(Signature)

Lead Hazard Control Clearance Soil Sampling Form

Date 3/11/13

Name of Clearance Examiner Ashley Wagon

License Number OKRASR13320, CNRASR00018

Name of Property Owner Betty Standlee

Property Address 28472 S. 4340 Rd. Vinita, OK 74301

| Sample Number | Location | Bare or Covered | Lab Result (mg/kg) | Pass or Fail |
|---------------|--------------------|-----------------|--------------------|--------------|
| 02 | Building perimeter | Bare | 46 | Pass |
| | | | | |
| | | | | |
| | | | | |

Total Number of Samples on this Page 1

Page 1 of 1

Date of Sample Collection 3/11/13

Date Shipped to Lab 3/12/13

Shipped by Ashley Wagon
(Signature)

Received by EMSL Analytical, Inc
(Signature)